COMPLETION REPORT

1. Name of Work : MAINTENANCE OF UGD IN WARD NO.12 SHETTYHALLI, SHETTYHALLI SUB DIVISION

3. Head of Account which is Chargeable :

4. Entrustment Order No. & Dt. :

5. Name of Contractor : M/S MAHENDRA ENGINEERING WORKS

6a. Time stipulated for completion of work :

b. Delay in Execution of work :

7. Measurement recorded in : M.B.No. 4870/2019-20.
Page No. 486907 to 486911

1. Check measurement of the Asst. : M.B.No. 4870/2019-20
Page No. 486907 to 486911

9. Name of the Office / Official In charge of the work :

10. a) Asst. Eng/ Junior Eng. : Shivakumar. A.P.

b) Asst. Exe. Engineer : Nagesh murthy.

Sanctioned estimate amount	Amount claims as per actually vide as per bills	DIFFERENCE	
		Excess	Savings

1. Certified that the above work has been completed within the stipulated time noted in the work order.
2. Certified that the contractor has delayed and completed the work for which necessary fine has been recovered.
3. Certified that the above work has been executed by the contractor satisfactorily in accordance with the specification as embodied in the agreement.

ASST. ENGINEER

ASST.EXE.ENGINEER
SHETTYHALLI SUB DIVISION
BRUHATH BANGALORE MAHANAGARA PALIKE

ACCOUNTS SUPTD.
DASARAHALLI DIVISION
BRUHATH BANGALORE MAHANAGARA PALIKE

EXECUTIVE ENGINEER
Bruhat Bengaluru Mahanagara Palike
Dasarahalli Division, Bengaluru-73.

Scanned by CamScanner